



## FORCE OUTPUT AND STROKE – TYPE 30 SERVICE CHAMBER - SECTION 8.0



## FORCE OUTPUT VERSUS STROKE (PARK CHAMBER) TYPE 30 - SECTION 7.0



Required parking force outputs are dependent on the requirements of the individual manufacturer. It is the duty of the manufacturer to test the vehicle in accordance with FMVSS121. The force values shown are after 24 hours set. Force output tolerances are  $\pm 10\%$ .